


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-046	Smoke	9/5/2008	ADS/TM	S13GG1026MH	Dry	Yes	768.37



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-046	Smoke	9/5/2008	ADS/TM	S13GG1026MH	Dry	Yes	768.37

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13GG1026G1	S13GG1026MH	S13GG1019MH	24.01927	8
S13GG1030G1	S13GG1030DE	S13GG1020MH	75.73818	8
S13II1033G1	S13II1033MH	S13GG1026MH	330.9391	8
S13GG1019G1	S13GG1019MH	S13GG1020MH	183.9726	8
S13GG1020G1	S13GG1020MH	S13GG1021MH	61.63160	8
S13II1053G1	S13II1053DE	S13II1033MH	92.07348	8

Observations & Photos

Obs_ID S1028-046-OB01

Address 4259 Park Heights Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S13GG1026MH

Comments Smoke from cleanout in back yard. 4259 Park Heights Ave.



Picture \S1028-046-OB01-P01.jpg

Comments Back of house, 4259 Park Heights Ave.